

Long Creek- Red Brook Comprehensive Watershed Assessment

Legend

- CH = channelization or "ditching" of the stream
- GC = golf course
- ISD = in-stream detention basin
- LF = landfill
- ND = new development since aerial photograph date
- PL = powerline and associated clearing of trees
- SCP = semi-conductor plant
- SE = severe erosion of streambank, terrace, or valley wall
- SPM = shading problems [moderate], sparse riparian tree canopy
- SPS = shading problems [severe], sparse riparian tree canopy
- SW = significant stormwater input (although not major)
- SWM = major stormwater input
- TR = trash in fairly heavy volume
- TRA = trash; automobile junkyard, although only a moderate presence of debris
- TRN = trash not greatly abundant, but noteworthy
- WM = stream/ditch converted into open water wetland (mitigation project)

Additional Legend Items

- Severe Problem
- Moderate Problem
- Watershed Boundary
- 3.0 Stream Mile

Figure 3.1.4d. Stream habitat walk and watershed survey findings for the Quadrant III (see Figure 3.1.4a). Numbers following the codes depicted on the map represent "survey site number". Site locations are approximated. Red text symbols indicate a major problem location. Aerial photographs dates are 1997-1998.

